

PICTURE 1

**IBM 170MB and 212MB  
AT Hard Disk Drives**

August, 1992

This supplement contains a Symptom-to-FRU Index and a parts listing for the IBM 170MB and 212MB AT Hard Disk Drives.

Insert this supplement in the IBM Personal System/2 *Hardware Maintenance Service* manual (part number 15F2200, form number SBOF-3988-00).

IBM and Personal System/2 are trademarks of the International Business Machines Corporation.

| Copyright International Business Machines Corporation 1992. All rights reserved.

Note to U.S. Government users-Documentation related to Restricted rights-Use, duplication, or disclosure is subject to restrictions set forth in GSA ADP Schedule Contract with IBM Corp.

Part Number 42G2343  
Form Number S42G-2343-00

## 170MB and 212MB AT Hard Disk Drives

### *1.0 170MB and 212MB AT Hard Disk Drives*

The 170MB and 212MB (MB = 1 000 000 bytes) 3.5-inch AT hard disk drives provide direct access storage device (DASD) storage for IBM Personal System/2 computers.

## Jumper Settings

### 2.0 Jumper Settings

The hard disk drives come preset as the first drive to be installed. If this is the second drive to be installed, find the jumper-block located on the bottom of the hard disk drive and set the jumper as shown below.

First Drive Installation	Second Drive Installation
PICTURE 2	PICTURE 3

## 3.0 Symptom-to-FRU Index

Error symptoms and the FRUs that might be responsible for the failure are listed below.

Error / Symptom	FRU / Action
17XX	Hard Disk Drive System Board

Parts Listing

4.0 Parts Listing

170MB AT Hard Disk Drive	95F4728
212MB AT Hard Disk Drive	93F0118
Mounting Tray	64F0141
Slide	96F7775

Printed in the U.S.A.