TABLE I DEPAECIATION TABLE FOA AESIDENTIAL/COMMEACIAL BUILDINGS MADE OF AEINFOACED CONCAETE AND MIXED CONCAETE MATERIAL'S

DEGREE OF MAINTENANCE	EXCELLENT		AVERAGE		POOR		
AGE YRS.	PERCENT DEPRECIATED	PERCENT GOOD	PERCENT DEPRECIATED	PERCENT GOOD	PERCENT DEPRECIATED	PERCENT GOOD	
0-2 2-5 5-8 8-12 12-16 16-20 20-25 25-30 30-35 35-40 40-45 45-50 50-55 55-60 60-65 65-70 70-75 75-80 80-85 85-90 90-95	3 5 8 11 15 18 21 25 28 31 34 36 39 42 45 48 51 54 57 60 63	97 95 92 89 85 82 79 75 72 69 65 62 59 55 52 49 45 42 43 40 37	3 5 9 14 18 22 25 28 31 34 37 40 43 46 49 52 55 58 61 64 67	97 95 91 86 85 79 75 72 69 66 63 60 57 54 61 48 45 42 39 36	4 7 11 16 20 24 29 33 37 41 45 49 51 54 56 59 62 65 68 70 73	96 93 89 84 80 76 71 67 63 59 55 52 49 46 44 41 38 35 32 30 27	
95-100	66	37 34	70	33 60	73 76	24	

\*EXCELLENT - The building at its present state does not need any repair or maintenance.

\*AVERAGE - At the time of appraisal, there are items in the subject building originally which

need slight repair or there is sign of deferred maintenance.

\*POOR - The building at present requires extensive repair and maintenance due to

deferred maintenance.

## OF TRONG MATERIALS, TYPE III - A, B, AND T

DEGREE OF MAINTENANCE	EXCE	ELLENT	AVERA	GE	POOR				
AGE YRS.	PERCENT DEPRECIATED	PERCENT GOOD	PERCENT DEPRECIATED	PERCENT GOOD	PERCENT DEPRECIATED	PERCENT GOOD			
0-2	4	96	4	96	5	95			
2-5	6	94	7	93	7	93			
5-8	11	89	12	87	15	85			
8-12	15	85	18	82	22	78			
12-16	19	81	23	77	29	71			
16-20	22	78	26	74	35	65			
20-25	25	75	30	670	41	59			
25-30	28	72	33	67	46	54			
30-35	31	69	37	63	50	50			
35-40	34	66	40	60	54	46			
40-45	37	62	44	56	57	43			
45-50	40	60	48	53	61	39			
50-55	44	56	50	50	64	36			
55-60	47	62	54	46	67	33			
60-65	50	50	57	43	70	30			
65-70	53	47	61	39	73	27			
70-75	56	44	64	36	75	25			

\*EXCELLENT - The building at its present state does not need any repair or maintenance.

\*AVERAGE - At the time of appraisal, there are items in the subject building originally which

need slight repair or there is sign of deferred maintenance.

\*POOR - The building at present requires extensive repair and maintenance due to

deferred maintenance.

DEGREE OF MAINTENANCE	EXCE	EXCELLENT AVERAGE			POOR		
AGE YRS.	PERCENT PERCENT DEPRECIATED GOOD D		PERCENT DEPRECIATED	PERCENT GOOD	PERCENT DEPRECIATED	PERCENT GOOD	
0-2	4	96	5	95	5	95	
2-5 5-8 8-12	10 18	90 82 75	14 22 30	86 78 70	14 24 35	86 76 65	
12-16 16-20	25 33 40	67 60	37 44	63 56	46 56	54 44	
20-25 25-30	47 55	53 45	52 60	48 40	65 72	35 28	
30-35	63	37	69	31	79	21	

#### DEPRECIATION OF BUILDING MADE OF LIGHT MATERIALS

0-2	5	95	6	94	6	94
2-5	12	88	13	87	13	87
5-8	23	77	27	73	30	70
8-12	32	68	38	62	44	56
12-16	41	59	47	53	57	43
16-20	51	49	57	43	68	32
20-25	62	38	68	32	78	22

\*EXCELLENT - The building at its present state does not need any repair or maintenance.

\*AVERAGE - At the time of appraisal, there are items in the subject building originally which

need slight repair or there is sign of deferred maintenance.

\*POOR - The building at present requires extensive repair and maintenance due to

deferred maintenance.

# OFFICE OF THE PROVINCIAL ASSESSOR PROVINCE OF OCCIDENTAL MINDORO

# SCHEDULE OF UNIT VALUES FOR BUILDING **GENERAL REVISION**

	(1)	(2)	(4)	(5)	(8)	(9)	(10)	(11)	(12)
	(1)	(2)	(4)	APARTMENT		(9)	(10)	(11)	(12)
TYPE	ONE	TWO	ACCESSORIA		BUILDING		OFFICE	THEATER	FACTORY
=	FAMILY	FAMILY	/ LOOLOGO I KII/ K	BOARDING	a) Garage		BUILDING	CHURCH	WAREHOUSE
	RESIDENCE	RESIDENCE	OR	HOUSE	b) Quarters	SCHOOL	COND.	ASSEMBLY	IND'S HOUSE
	1120.52.102	(3)	J	(7)	c) Laundry	00002	HOSPITAL	HOUSE	HANGERS
		MULTIPLE	TOWN	LODGING	House		HOTEL		
		DWELLING	HOUSE	HOUSE	d) Guard	BUILDING			
				MOTEL	House				
					etc.				
I	P 600	P 750	P 750	P 900	Р -	Р -	Р -	Р -	Р -
II-A	2250	2070	1880	2450	1880	1880	2820	2820	1500
II-B	1880	1700	1500	2070	1500	1700	2530	2440	1320
II-C	1700	1400	1320	1700	1120	1400	2070	2070	1120
II-D	1320	1120	1120	1320	750	1120	-	-	750
II-E	1050	1030	1030	1220	-	-	-	-	-
III-A	5180	4270	4050	4720	4050	4270	4950	4950	3150
III-B	4050	3820	3600	4270	3600	3820	4500	4500	2700
III-C	3600	3370	3150	3820	3150	3370	4050	4270	2370
III-D	3150	2920	2700	3370	2700	2920	3600	3820	2150
IV-A	7100	7800	5780	6570	4270	6690	7100	7250	5250
IV-B	6200	5200	4950	5700	3450	5940	6200	6430	4450
							l		
V	9000	7800	7200	-	-	8100	9000	9000	6600

## INCREMENT TO BASIC UNIT MARKET VALUE FOR BUILDINGS AND OTHER STRUCTURE:

### 1. Foundation:

- III Foundation area x 310 x No. of floors
- IV Foundation area x 450 x No. of floors V Foundation area x 660 x No. floors

## 2. Flooring:

- 2.1 Granolithic, linotile, vinyl, asphalt and wood tiles, add P300 to P420/sq.m. to affected area
   2.2 Crazy-cut marble, add P600/sq.m. to affected area

#### 3. Walling and Partitioning:

- 3.1 Marble, add P600/sq.m. to affected area
- 3.2 Synthetic Marble and other finish, add P360 to P510 to P450/sq.m. to affected area

## 4. Ceiling:

- 4.1 Ordinary drop ceiling on R.C. bldg. Add P150/sq.m. to affected area
- 4.2 Luminous, add P180/sq.m.
- 4.3 Narra and other special panels, add P210/sq.m.

# OFFICE OF THE PROVINCIAL ASSESSOR PROVINCE OF OCCIDENTAL MINDORO

## SCHEDULE OF UNIT VALUES FOR BUILDING **GENERAL REVISION**

	(13)	(14)	(15)	(16)	(17)	(18)	(19)	
TYPE	MARKET SHOPPING CENTER	GYMNASIUM COLLISEUM	RECREATION a) B. LANDS b) CLUB	SAW MILLS AND LUMBER SHEDS	GASOLINE STATION GAS REFILLING	SWIMMING POOL & BATH HOUSE	BARN HOUSE POULTRY GRAIN HOUSE LIVE- STOCK	
I II-A II-B II-C II-D II-E	P - 2070 1700 1320 950	P - 2070 1700 1320 - -	P - - - - -	P - 2070 1700 1320 1030 840	P - - - - -	P	P 300 1700 1320 1120 950 570	
III-A III-B III-C III-D	5780 3820 3380 2920	4270 3820 3370 2920	3600 3150 -	- - 3050 2750	4050 3600 3150 -	- - -	- - - 2700	
IV-A IV-B	6040 5200	5250 3270	5780 4950	- -	- 4950	- -	- -	
V	6000	6600	7200	-	7800	4800-9000	-	

- 5. Special Aluminum Glass Panel:
  - 5.1 Ordinary size add P240 to P390/sq.m.
  - 5.2 Foundation area x 450 x No. of floors
- 6. Height:
  - $6.1\,$   $\,$  Excess height add 10% for every meter from the basic rate
  - 6.2 Deficiency in heigh subtract 10% for every meter from the basic rate
    - Standard Height 2.40- meters for one storey 2.70- meters for two storey 11.80- meters for mezzanine

- 7. Terrace:
  - 7.1 Open Area x 40% of Basic Rate
  - 7.2 Covered (no siding) Area x 50% of Basic Rate
- 8. Other Increment to Basic Unit Value Not Herein Specifie

Shall be applied at 75% of its actual construction.

- 9. All Basic Unit Value applicable to ground floor area

  \* Swimming Pools the volume (cu.m. is one of the factors in determining the market value - hence, the proposed value is presented in rage/bracket.

# SCHEDULE OF UNIT VALUES FOR BUILDING GENERAL REVISION

	(13)	(14)	(15)	(16)	(17)	(18)	(19)	
TYPE	MARKET SHOPPING CENTER	GYMNASIUM COLLISEUM	RECREATION a) B. LANDS b) CLUB	SAW MILLS AND LUMBER SHEDS	GASOLINE STATION GAS REFILLING	SWIMMING POOL & BATH HOUSE	BARN HOUSE POULTRY GRAIN HOUSE LIVE- STOCK	
I II-A II-B II-C II-D II-E	P - 2070 1700 1320 950 - 5200	P - 2070 1700 1320 	P 4050	P - 2070 1700 1320 1030 840	P	P	P 300 1700 1320 1120 950 570	
III-B	3820	3820	3600	-	3600	-	-	
III-C III-D	3380 2920	3370 2920	3150 -	3050 2750	3150 -	-	2700	
IV-A IV-B V	6000 5780 60040	5250 3270 6600	5780 4950 7200	-	- 4950 7800	- - 4800-9000	-	

- 5. Special Aluminum Glass Panel:
  - 5.1 Ordinary size add P240 to P390/sq.m.
  - 5.2 Foundation area x 450 x No. of floors
- 6. Height:
  - 6.1 Excess height add 10% for every meter from the basic rate
  - 6.2 Deficiency in heigh subtract 10% for every meter from the basic rate
    - \* Standard Height
      - 2.40- meters for one storey
      - 2.70- meters for two storey
      - 11.80- meters for mezzanine

#### 7. Terrace:

- 7.1 Open Area x 40% of Basic Rate
- 7.2 Covered (no siding) Area x 50% of Basic Rate
- 8. Other Increment to Basic Unit Value Not Herein Specifie

Shall be applied at 75% of its actual construction.

- 9. All Basic Unit Value applicable to ground floor area
  - \* Swimming Pools the volume (cu.m. is one of the factors in determining the market value hence, the proposed value is presented in rage/bracket.



